

## CENTIGRADE - FAHRENHEIT

C	F	C	F	C	F	C	F
-80	-112.0	9	48.2	47	116.6	85	185.0
-70	-94.0	10	50.0	48	118.4	86	186.8
-60	-76.0	11	51.8	49	120.2	87	188.6
-50	-58.0	12	53.6	50	122.0	88	190.4
-45	-49.1	13	55.4	51	123.8	89	192.2
-40	-40.0	14	57.2	52	125.6	90	194.0
-35	-31.0	15	59.0	53	127.4	91	195.8
-30	-22.0	16	60.8	54	129.2	92	197.6
-25	-13.0	17	62.6	55	131.0	93	199.4
-20	-4.0	18	64.4	56	132.8	94	201.2
-19	-2.2	19	66.2	57	134.6	95	203.0
-18	-0.4	20	68.0	58	136.4	96	204.8
-17	1.4	21	69.8	59	138.2	97	206.6
-16	3.2	22	71.6	60	140.0	98	208.4
-15	5.0	23	73.4	61	141.8	99	210.2
-14	6.8	24	75.2	62	143.6	100	212.0
-13	8.6	25	77.0	63	145.4	105	221.0
-12	10.4	26	78.8	64	147.2	110	230.0
-11	12.2	27	80.6	65	149.0	115	239.0
-10	14.0	28	82.4	66	150.8	120	248.0
-9	15.8	29	84.2	67	152.6	130	266.0
-8	17.6	30	86.0	68	154.4	140	284.0
-7	19.4	31	87.8	69	156.2	150	302.0
-6	21.2	32	89.6	70	158.0	160	320.0
-5	23.0	33	91.4	71	159.8	170	338.0
-4	24.8	34	93.2	72	161.6	180	356.0
-3	26.6	35	95.0	73	163.4	190	374.0
-2	28.4	36	96.8	74	165.2	200	392.0
-1	30.2	37	98.6	75	167.0	250	482.0
0	32.0	38	100.4	76	168.8	300	572.0
1	33.8	39	102.2	77	170.6	350	662.0
2	35.6	40	104.0	78	172.4	400	752.0
3	37.4	41	105.8	79	174.2	500	932.0
4	39.2	42	107.6	80	176.0	600	1112.0
5	41.0	43	109.4	81	177.8	700	1292.0
6	42.8	44	111.2	82	179.6	800	1472.0
7	44.6	45	113.0	83	181.4	900	1652.0
8	46.4	46	114.8	84	183.2	1000	1832.0

$$C = 5/9 (F - 32)$$

$$F = 9/5 \cdot C + 32, \text{ or } 9/5C + 32$$